

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name: _____ **Date of Construction:** c. 1910
Common Name: _____ **Original Use:** Church
Address: 1719 Cedar Street **Present Use:** Church
City: Forest Grove **Architect:** _____
Zoning: A1 **Builder:** _____
T/R/S: T. 1S., R. 3 W. Sec. 6 **Theme:** Culture: Religion
Map No.: 1 S 3 6BD **Tax Lot:** 800 **Style:** Craftsman
Addition: Original Town Plat
Block: 31 **Lot:** 4 **Quad:** USGS Forest Grove 7.5' **Building** **Structure** **Site**

Plan Type/Shape: Rectangular **Number of Stories:** 1
Foundation Material: Concrete and Brick **Basement (Y/N):** N
Roof Form and Materials: Gable with composition shingles
Wall Construction: Wood **Structural Frame:** Stud
Primary Window Type: 1/1 DHS, 10/1 bungalow, some with aluminum storm windows
Exterior Surfacing Materials: Shiplap with cornerboards and watertable
Decorative Features: Purlins and braces; bargeboards; exposed rafters; stickwork
Other : Enclosed gable roof porch on W elevation; 5 panel double doors
Condition: Good Fair Poor Moved _____ (Date):
Integrity: Virtually Intact Minor Alterations Major Alterations

Exterior Alterations/Additions (Dated): Gable and shed roof additions to rear elevation; doors replaced; attached to modular structures to the rear

Noteworthy Landscape Features:

Associated Structures:

Known Archaeological Features:

Setting: 1719 Cedar is located on the east side of Cedar Street. The area is largely residential and traffic is light.

Negative No.: _____
Slide No.: _____

Recorded By: Peter J. Edwards, *Columbia Historical Research*
Date: August 1993

Resource #: _____

SHPO Inventory No.: _____

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**


Name :
Address: 1719 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BD Tax Lot: 800
Quadrangle: USGS Forest Grove 7.5'



Negative No.: Roll

Slide No. :



**SKETCH OF
STRUCTURE**

Graphic and Photo Sources: City of Forest Grove, Peter J. Edwards *CHR*, Forest Grove Historic Landmarks Board

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**

Name :
Address: 1719 Cedar Street
Resource #:


T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BD **Tax Lot:** 800
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

It is unclear what church first occupied this building. The Seventh Day Adventist Church was a long time owner, but it is not certain if they were the first occupants.

Craftsman public buildings were common during the period from 1910-1925. Grange halls, city halls, and churches of modest size all used the basic Craftsman form that was being perfected in residential neighborhoods all over America.

This building has been added to in the rear, but the basic form of the original building has been retained.



**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name: _____ **Date of Construction:** c. 1920
Common Name: _____ **Original Use:** Residence
Address: 1723 Cedar Street **Present Use:** Residence
City: Forest Grove **Architect:** _____
Zoning: A1 **Builder:** _____
T/R/S: T. 1S., R. 3 W. Sec. 6 **Theme:** Culture: 20th C. Architecture
Map No.: 1 S 3 6BD **Tax Lot:** 700 **Style:** Vernacular
Addition: Original Town Plat
Block: 31 **Lot:** 2 **Quad:** USGS Forest Grove 7.5' **Building** **Structure** **Site**

Plan Type/Shape: Rectangular **Number of Stories:** 1.5
Foundation Material: Concrete **Basement (Y/N):** N
Roof Form and Materials: Gable with composition shingles
Wall Construction: Wood **Structural Frame:** Stud
Primary Window Type: 1/1 DHS, 4/1 bungalow
Exterior Surfacing Materials: Clapboard
Decorative Features: Applied decorative shutters
Other : Shed roof porch on W elevation; 15 pane entry door
Condition: Good Fair Poor Moved _____ (Date):
Integrity: Virtually Intact Minor Alterations Major Alterations

Exterior Alterations/Additions (Dated): Shed porch is a replacement

Noteworthy Landscape Features:

Associated Structures: Garage on NE corner of house

Known Archaeological Features:

Setting: 1723 Cedar is located on the E side of Cedar Street. The area is residential and traffic is light.

Negative No.: _____
Slide No.: _____

Recorded By: Peter J. Edwards, *Columbia Historical Research*
Date: August 1993


Resource #: _____

SHPO Inventory No.: _____

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**


Name :
Address: 1723 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BD Tax Lot: 700
Quadrangle: USGS Forest Grove 7.5'



Negative No.: Roll

Slide No. :



**SKETCH OF
STRUCTURE**

Graphic and Photo Sources: City of Forest Grove, Peter J. Edwards *CHR*, Forest Grove Historic Landmarks Board

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**

Name :
Address: 1723 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BD **Tax Lot:** 700
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

This simple house was built during the transition from the Craftsman style to smaller picturesque styles like Cape Cod Colonial. The house has a bungalow window, but none of the other Craftsman decorative elements.

Little is known about the history of the house.

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name:	Date of Construction: c. 1920
Common Name:	Original Use: Residence
Address: 1729 Cedar Street	Present Use: Residence
City: Forest Grove	Architect:
Zoning: A1	Builder:
T/R/S: T. 1S., R. 3 W. Sec. 6	Theme: Culture: 20th C. Architecture
Map No.: 1 S 3 6BD Tax Lot: 600	Style: Prairie
Addition: Original Town Plat	
Block: Lot: Quad: USGS Forest Grove 7.5'	Building <input checked="" type="checkbox"/> Structure <input type="checkbox"/> Site <input type="checkbox"/>

Plan Type/Shape: Rectangular	Number of Stories: 1
Foundation Material: Concrete	Basement (Y/N): N
Roof Form and Materials: Hip with composition shingles	
Wall Construction: Stone	Structural Frame: Masonry
Primary Window Type: 1/1 DHS with aluminum storm windows, 4 pane casement	
Exterior Surfacing Materials: Cast stone	
Decorative Features: None	
Other : Shed roof porch on W elevation [not original]	
Condition: Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Moved _____ (Date):	
Integrity: Virtually Intact <input type="checkbox"/> Minor Alterations <input checked="" type="checkbox"/> Major Alterations <input type="checkbox"/>	

Exterior Alterations/Additions (Dated): Porch replacement; storm windows added

Noteworthy Landscape Features:

Associated Structures: Carport with gable roof to NW of house

Known Archaeological Features:

Setting: 1729 Cedar is located on the E side of Cedar. The area is residential and traffic is light.

Negative No.:
Slide No.:

Recorded By: Peter J. Edwards, *Columbia Historical Research*
Date: August 1993

Resource #:

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**


Name :
Address: 1729 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BD Tax Lot: 600
Quadrangle: USGS Forest Grove 7.5'



Negative No.: Roll

Slide No. :



**SKETCH OF
STRUCTURE**

Graphic and Photo Sources: City of Forest Grove, Peter J. Edwards *CHR*, Forest Grove Historic Landmarks Board

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**

Name :
Address: 1729 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BD Tax Lot: 600
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

This unique house takes a bit of influence from the early 20th century work of Frank Lloyd Wright. The Prairie style, heavily influenced by Wright, featured low pitched roofs, casement windows groups in continuous bands, and rectangular ground hugging composition. These features are all found in this vernacular adaptation of the Prairie style.

The cast stone of this house substitutes for brick or stucco preferred by the Prairie style, but the other elements are clear. The house has a definite ground hugging feel and the roof is so low pitched and an attic is probably impractical.

The history of this house is unclear. According to local informants, a Mr. Knee designed the house. There is no such person in the 1920 census for Forest Grove.

Sources: US Bureau of the Census, 1920.
 Clark, *Architecture Oregon Style*, 1983.
 City Files, 1729 Cedar, 1993.

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name: William/Elizabeth Geiger House

Date of Construction: c. 1860

Common Name:

Original Use: Residence

Address: 1804 Cedar Street

Present Use: Residence/Multi-family

City: Forest Grove

Architect:

Zoning: A2

Builder:

T/R/S: T. 1S., R. 3 W. Sec. 6

Theme: Culture: 19th C. Architecture

Map No.: 1 S 3 6BA **Tax Lot:** 9200

Style: Vernacular

Addition: Original Town Plat

Block: 21 **Lot:** 1 **Quad:** USGS Forest Grove 7.5' **Building** **Structure** **Site**

Plan Type/Shape: Rectangular

Number of Stories: 2

Foundation Material: Coursed Stone

Basement (Y/N): N

Roof Form and Materials: Gable, with composition shingles

Wall Construction: Wood

Structural Frame: Stud.

Primary Window Type: 1/1 DHS

Exterior Surfacing Materials: Shiplap with cornerboards and watertable

Decorative Features: Frieze, brackets on rear shed porch, corbeled chimney cap

Other : Gable lean to off rear elevation, enclosed mansard roof porch on S elevation, shed porch on S elevation — attached to gable lean to

Condition: Good Fair Poor Moved _____ (Date):

Integrity: Virtually Intact Minor Alterations Major Alterations

Exterior Alterations/Additions (Dated): Rear gable roof lean to added c. 1875; S elevation mansard porch added c. 1875

Noteworthy Landscape Features:

Associated Structures:

Known Archaeological Features:

Setting: 1804 Cedar is located on the NW corner of 18th and Cedar. The area is residential.

Negative No.:

Recorded By: Peter J. Edwards, *Columbia Historical Research*

Slide No.:

Date: August 1993

Resource #:

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**


Name : Geiger House
Address: 1804 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA Tax Lot: 9200
Quadrangle: USGS Forest Grove 7.5'



Negative No.: Roll

Slide No. :



**SKETCH OF
STRUCTURE**

Graphic and Photo Sources: City of Forest Grove, Peter J. Edwards *CHR*, Forest Grove Historic Landmarks Board

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**

Name : Geiger House
Address: 1804 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA Tax Lot: 9200
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

The precise history of this house is unknown. Some property records exist for Block 21 and they show that Stephen Halcomb obtained land in Block 21 from J. M. Keeler in 1856.

Halcomb was born in New York in 1822/23. He married Amanda (b. 1833/34 in Oregon) in Oregon sometime before 1853. If the 1833 date for Amanda's birth is correct, it is likely that she was the child of some of the early missionaries to settle in Oregon. In 1860 they had 4 children and were living in Forest Grove. Stephen was employed as a farmer.

Halcomb sold the property to William Geiger in 1866. Geiger (b. 1816 in New York) was one of the significant early residents of Forest Grove, having lived there on and off since his arrival in Oregon in the late 1830's. Geiger's wife Elizabeth was born in Arkansas in 1829 and they married after her arrival in Oregon sometime prior to 1848. His eldest child, William, was born in Oregon in 1848/49. Geiger was a physician in Forest Grove. In 1870 William and Elizabeth were living with their 8 children in town.

It is unclear exactly when the house was built, but the time frame of 1856-1860 is likely. The addition of a mansard porch to the south elevation provides a link to the period of the Second Empire style in Oregon. Second Empire style was popular between 1865 and 1880 in Oregon. Given that the mansard roof porch is a likely addition to the original house, a date c. 1860 for construction of the original house is likely. The rapid growth of the Geiger family was at the heart of the addition as 8 children occupied the house by 1870.

The Geiger's were a close family and most members stayed in Forest Grove. 1st child William C. was working as a physician and living with the family in 1880. In 1900 the Geiger's were still living in the house at the ages of 83 and 70, respectively. A son, Hubert, was living with them and working as a dentist. 3rd child Charles E. Geiger and his family lived on the north side of Block 21, and 8th child Laura B. Wells, who was widowed by age 29 in 1900 also lived on Block 21. Charles was a physician in 1900.

The house as of 1993 is being used for apartments, with the original residence converted on the interior into 3 separate units.

Sources: US Bureau of the Census, 1860
US Bureau of the Census, 1870
US Bureau of the Census, 1880.
US Bureau of the Census, 1900.
US Bureau of the Census, 1910.
Clark, *Architecture Oregon Style*, 1983.
City Files, 1804 Cedar, 1993.

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name: _____ **Date of Construction:** c. 1890
Common Name: _____ **Original Use:** Residence
Address: 1817 Cedar Street **Present Use:** Residence
City: Forest Grove **Architect:** _____
Zoning: A2 **Builder:** _____
T/R/S: T. 1S., R. 3 W. Sec. 6 **Theme:** Culture: 19th C. Architecture
Map No.: 1 S 3 6BA **Tax Lot:** 10200 **Style:** Vernacular
Addition: Original Town Plat
Block: 20 **Lot:** 4 **Quad:** USGS Forest Grove 7.5' **Building** **Structure** **Site**

Plan Type/Shape: Assymetrical **Number of Stories:** 1.5
Foundation Material: Unknown **Basement (Y/N):** N
Roof Form and Materials: Gable with composition shingles
Wall Construction: Wood **Structural Frame:** Stud.
Primary Window Type: 1/1 DHS with lintels and aluminum storm windows
Exterior Surfacing Materials: Wide dropped siding c. 1955.
Decorative Features: Frieze; decorative recessed wood panels on polygonal window bay on N elevation
Other : Full width hip roof porch on W elevation; 5 panel, 5 lite entry door with transom on W elevation; polygonal window bay on N elevation; gable roof Ell on S, E elevations
Condition: Good Fair Poor Moved ____ (Date):
Integrity: Virtually Intact Minor Alterations Major Alterations

Exterior Alterations/Additions (Dated): Siding replaced, c. 1955. Semi-attached gable Ell added to E elevation. Decorative woodwork on porch removed, n.d.

Noteworthy Landscape Features:

Associated Structures:

Known Archaeological Features:

Setting: 1817 Cedar is located on the E side of Cedar Street , less than a block south of busy 19th Avenue. The area is zoned for multi-family, but is near a commercially zoned area.

Negative No.: _____
Slide No.: _____

Recorded By: Peter J. Edwards, *Columbia Historical Research*
Date: August 1993

Resource #: _____

SHPO Inventory No.: _____

CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM

Name :
Address: 1817 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA Tax Lot: 10200
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

This 19th century vernacular house with Queen Anne and Stick elements has been extensively altered. The siding was replaced in the 1950's. In addition, a large gable addition has been made to the house on the E or rear elevation.

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name: _____ **Date of Construction:** c. 1943
Common Name: _____ **Original Use:** Residence
Address: 1828 Cedar Street **Present Use:** Residence
City: Forest Grove **Architect:** _____
Zoning: CA **Builder:** _____
T/R/S: T. 1S., R. 3 W. Sec. 6 **Theme:** Culture: 20th C. Architecture
Map No.: 1 S 3 6BA **Tax Lot:** 9500 **Style:** Vernacular
Addition: Original Town Plat
Block: 21 **Lot:** 2 **Quad:** USGS Forest Grove 7.5' **Building** **Structure** **Site**

Plan Type/Shape: Rectangular **Number of Stories:** 1
Foundation Material: Concrete **Basement (Y/N):** Unk
Roof Form and Materials: Hip with composition shingles
Wall Construction: Wood **Structural Frame:** Stud.
Primary Window Type: 6/6 DHS with aluminum storm windows
Exterior Surfacing Materials: Wide dropped siding
Decorative Features: None
Other : Gable roof porch on E elevation with purlins and braces; 1 panel, 1 lite entry door
Condition: Good Fair Poor Moved _____ (Date):
Integrity: Virtually Intact Minor Alterations Major Alterations

Exterior Alterations/Additions (Dated): None

Noteworthy Landscape Features:

Associated Structures: Hip roof garage located to N of house.

Known Archaeological Features:

Setting: 1828 Cedar is located on the W side of Cedar Street just south of busy 19th Avenue. The area is zoned for commercial use.

Negative No.: _____
Slide No.: _____

Recorded By: Peter J. Edwards, *Columbia Historical Research*
Date: August 1993

Resource #: _____

SHPO Inventory No.: _____

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**


Name :
Address: 1828 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA **Tax Lot:** 9500
Quadrangle: USGS Forest Grove 7.5'



Negative No.: Roll

Slide No. :



**SKETCH OF
STRUCTURE**

Graphic and Photo Sources: City of Forest Grove, Peter J. Edwards *CHR*, Forest Grove Historic Landmarks Board

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**

Name :
Address: 1828 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA **Tax Lot:** 9500
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

1828 Cedar is a good example of the simple unadorned houses built between 1935 and 1950. It has not been altered appreciably since being constructed in 1943.

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name: _____ **Date of Construction:** 1943
Common Name: _____ **Original Use:** Residence
Address: 1838 Cedar Street **Present Use:** Residence
City: Forest Grove **Architect:** _____
Zoning: CA **Builder:** _____
T/R/S: T. 1S., R. 3 W. Sec. 6 **Theme:** Culture: 20th C. Architecture
Map No.: 1 S 3 6BA **Tax Lot:** 9600 **Style:** Vernacular
Addition: Original Town Plat
Block: 21 **Lot:** 2 **Quad:** USGS Forest Grove 7.5' **Building** **Structure** **Site**

Plan Type/Shape: Rectangular **Number of Stories:** 1
Foundation Material: Concrete **Basement (Y/N):** N
Roof Form and Materials: Gable with composition shingles
Wall Construction: Wood **Structural Frame:** Stud.
Primary Window Type: 6/1 DHS with aluminum storm windows
Exterior Surfacing Materials: clapboard with cornerboards
Decorative Features: None
Other : Hip on gable roof porch on E elevation; 3 panel 3 light entry door; gable roof Ell on W elevation.
Condition: Good Fair Poor Moved _____ (Date):
Integrity: Virtually Intact Minor Alterations Major Alterations

Exterior Alterations/Additions (Dated): Gable Ell added to rear of house (nd); breezeway built between house and garage.

Noteworthy Landscape Features:

Associated Structures: Gable roof garage to SW

Known Archaeological Features:

Setting: 1838 Cedar is located on the SW corner of 19th Avenue and Cedar Street. Traffic is heavy on 19th Avenue and the area is zoned for commercial use.

Negative No.: _____
Slide No.: _____

Recorded By: Peter J. Edwards, *Columbia Historical Research*
Date: August 1993


Resource #: _____

SHPO Inventory No.: _____

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**


Name :
Address: 1838 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA Tax Lot: 9600
Quadrangle: USGS Forest Grove 7.5'



Negative No.: Roll

Slide No. :



**SKETCH OF
STRUCTURE**

Graphic and Photo Sources: City of Forest Grove, Peter J. Edwards *CHR*, Forest Grove Historic Landmarks Board

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**

Name :
Address: 1838 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA **Tax Lot:** 9600
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

This house, like its neighbor to the south, was built in 1943 and demonstrates the limited financial means of those times. It lacks ornament and is simple and small. It has been altered to include a gable addition to the rear and an attachment to a garage to the SW.

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name: _____ **Date of Construction:** c. 1915
Common Name: _____ **Original Use:** Residence
Address: 1909 Cedar Street **Present Use:** Residence
City: Forest Grove **Architect:** _____
Zoning: CBD **Builder:** _____
T/R/S: T. 1S., R. 3 W. Sec. 6 **Theme:** Culture: 20th C. Architecture
Map No.: 1 S 3 6BA **Tax Lot:** 2800 **Style:** Craftsman
Addition: Original Town Plat
Block: 9 **Lot:** 4 **Quad:** USGS Forest Grove 7.5' **Building** **Structure** **Site**

Plan Type/Shape: Rectangular **Number of Stories:** 1.5
Foundation Material: Concrete **Basement (Y/N):** Y
Roof Form and Materials: Gable, with composition shingles
Wall Construction: Wood **Structural Frame:** Stud.
Primary Window Type: 1/1 DHS with aluminum storm windows; 1 pane fixed aluminum windows.
Exterior Surfacing Materials: Non-original wide dropped siding
Decorative Features: Exposed rafters
Other : Gable roof porch W elevation; partially enclosed shed roof porch on N elevation; rectangular and polygonal window bays on N elevation; exterior end wall chimney, W elevation.
Condition: Good Fair Poor Moved _____ (Date):
Integrity: Virtually Intact Minor Alterations Major Alterations

Exterior Alterations/Additions (Dated): Siding replaced, c. 1950; battered porch posts removed, replaced with metal, c.1950. Brick piers remain. Bargeboards also removed.

Noteworthy Landscape Features:

Associated Structures:

Known Archaeological Features:

Setting: 1909 Cedar is located on the E side of Cedar Street near busy 19th Avenue. The area is zoned commercial

Negative No.: _____
Slide No.: _____

Recorded By: Peter J. Edwards, *Columbia Historical Research*
Date: August 1993

Resource #: _____

SHPO Inventory No.: _____

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**


Name :
Address: 1909 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BB Tax Lot: 2800
Quadrangle: USGS Forest Grove 7.5'



Negative No.: Roll

Slide No. :



**SKETCH OF
STRUCTURE**

Graphic and Photo Sources: City of Forest Grove, Peter J. Edwards *CHR*, Forest Grove Historic Landmarks Board

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**

Name :
Address: 1909 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA **Tax Lot:** 2800
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

1909 Cedar suffers from major alterations dating to the 1950's which removed the bungalow style battered porch posts, although the brick piers are still visible. The alterations also included the replacement of the siding and the removal of the bargeboards.

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name: _____ **Date of Construction:** c. 1915
Common Name: _____ **Original Use:** Residence
Address: 1913 Cedar Street **Present Use:** Residence
City: Forest Grove **Architect:** _____
Zoning: CA **Builder:** _____
T/R/S: T. 1S., R. 3 W. Sec. 6 **Theme:** Culture: 20th C. Architecture
Map No.: 1 S 3 6BA **Tax Lot:** 2700 **Style:** Craftsman
Addition: Original Town Plat
Block: 9 **Lot:** 4 **Quad:** USGS Forest Grove 7.5' **Building** **Structure** **Site**

Plan Type/Shape: Rectangular **Number of Stories:** 1
Foundation Material: Concrete **Basement (Y/N):** N
Roof Form and Materials: Hip on Gable, composition shingles
Wall Construction: Wood **Structural Frame:** Stud.
Primary Window Type: 6/1 DHS with aluminum storm windows; 6 pane casement; 24 pane fixed.
Exterior Surfacing Materials: Wide dropped siding with cornerboards.
Decorative Features: Purlins and braces, exposed rafters.
Other : Enclosed shed roof porch on W elevation
Condition: Good Fair Poor Moved ____ (Date):
Integrity: Virtually Intact Minor Alterations Major Alterations

Exterior Alterations/Additions (Dated): Large hip on gable rear addition. The addition is similar in size and scale to the original house and was probably added soon after the original house was built.

Noteworthy Landscape Features:

Associated Structures:

Known Archaeological Features:

Setting: 1913 Cedar is located on the east side of Cedar Street between busy Pacific and 19th Avenues. The area is zoned for commercial use.

Negative No.: _____
Slide No.: _____

Recorded By: Peter J. Edwards, *Columbia Historical Research*
Date: August 1993

Resource #: _____

SHPO Inventory No.: _____

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**


Name :
Address: 1913 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6B Tax Lot: 2700
Quadrangle: USGS Forest Grove 7.5'



Negative No.: Roll

Slide No. :



**SKETCH OF
STRUCTURE**

Graphic and Photo Sources: City of Forest Grove, Peter J. Edwards *CHR*, Forest Grove Historic Landmarks Board

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**

Name :
Address: 1913 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA **Tax Lot:** 2700
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

1913 Cedar Street is a simple bungalow type home which was doubled in size by a rear addition. It has minimal bungalow ornament. The property is zoned commercial

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name: _____ **Date of Construction:** c. 1908
Common Name: _____ **Original Use:** Residence
Address: 1919 Cedar Street **Present Use:** Residence
City: Forest Grove **Architect:** _____
Zoning: CA **Builder:** _____
T/R/S: T. 1S., R. 3 W. Sec. 6 **Theme:** Culture: 20th C. Architecture
Map No.: 1 S 3 6BA **Tax Lot:** 2600 **Style:** Vernacular
Addition: Original Town Plat
Block: 9 **Lot:** 4 **Quad:** USGS Forest Grove 7.5' **Building** **Structure** **Site**

Plan Type/Shape: Rectangular **Number of Stories:** 1.5
Foundation Material: Wood posts on concrete piers **Basement (Y/N):** N
Roof Form and Materials: Gable, composition shingles
Wall Construction: Wood **Structural Frame:** Stud.
Primary Window Type: 1/1 DHS with plain surrounds and aluminum storm windows; some sliding aluminum
Exterior Surfacing Materials: Wide dropped with cornerboards and watertable
Decorative Features: Frieze
Other : Full width enclosed shed roof porch, W elevation; gable roof Ell, E elevation
Condition: Good Fair Poor Moved ____ (Date):
Integrity: Virtually Intact Minor Alterations Major Alterations

Exterior Alterations/Additions (Dated): Front porch enclosed and skylights added on W. elevation between 1984 and 1993.

Noteworthy Landscape Features:

Associated Structures:

Known Archaeological Features:

Setting: 1919 Cedar is located on the east side of Cedar Street between busy Pacific and 19th Avenues. The area is zoned for commercial use.

Negative No.: _____
Slide No.: _____

Recorded By: Peter J. Edwards, *Columbia Historical Research*
Date: August 1993

Resource #: _____

SHPO Inventory No.: _____

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**


Name :
Address: 1919 Cedar
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BB Tax Lot: 2600
Quadrangle: USGS Forest Grove 7.5'



Negative No.: Roll

Slide No. :



**SKETCH OF
STRUCTURE**

Graphic and Photo Sources: City of Forest Grove, Peter J. Edwards *CHR*, Forest Grove Historic Landmarks Board

SHPO Inventory No.:

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**

Name :
Address: 1919 Cedar
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA **Tax Lot:** 2600
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

This vernacular home was significantly altered between 1984 and 1993. The front porch was fully enclosed and converted to a sitting room. Skylights were added to the roof on the W side. The original siding and many original windows remain, however. The area is zoned commercial and lies between the 2 main streets of Forest Grove.

Sources: City Files, 1919 Cedar, 1993.

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM
WASHINGTON COUNTY, OREGON**

Historic Name: _____ **Date of Construction:** c. 1880
Common Name: _____ **Original Use:** Residence
Address: 1928 Cedar Street **Present Use:** Residence
City: Forest Grove **Architect:** _____
Zoning: CBD **Builder:** _____
T/R/S: T. 1S., R. 3 W. Sec. 6 **Theme: Culture:** 19th C. Architecture
Map No.: 1 S 3 6BA **Tax Lot:** 3600 **Style:** Gothic Revival
Addition: Original Town Plat
Block: 8 **Lot:** 2 **Quad:** USGS Forest Grove 7.5' **Building** **Structure** **Site**

Plan Type/Shape: Rectangular **Number of Stories:** 2
Foundation Material: Brick piers **Basement (Y/N):** N
Roof Form and Materials: Cross - Gable with composition shingles
Wall Construction: Wood **Structural Frame:** Stud.
Primary Window Type: Narrow 1/1 DHS with gabled lintels
Exterior Surfacing Materials: Shiplap, with cornerboards and watertable
Decorative Features: Frieze
Other : Full width shed roof porch on E elevation; 1 panel, glazed door; Hip roof Ell on W elevation, attached to shed roof Ell on W elevation
Condition: Good Fair Poor Moved ____ (Date):
Integrity: Virtually Intact Minor Alterations Major Alterations

Exterior Alterations/Additions (Dated): Hip Ell was previously a porch. Porch was enclosed. Later, a shed roof Ell was added. Some decorative elements were lost off of the front porch.

Noteworthy Landscape Features: Overgrown plantings threaten the E or front elevation of the house and obscure the view.

Associated Structures:

Known Archaeological Features:

Setting: 1928 Cedar is located on the W side of Cedar Street between busy 19th and Pacific Avenues. The area is zoned for the central business district. A large vacant lot is directly to the north.

Negative No.: _____
Slide No.: _____

Recorded By: Peter J. Edwards, *Columbia Historical Research*
Date: August 1993

Resource #: _____

SHPO Inventory No.: _____

**CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM**


Name :
Address: 1928 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BB Tax Lot: 3600
Quadrangle: USGS Forest Grove 7.5'



Negative No.: Roll

Slide No. :



**SKETCH OF
STRUCTURE**

Graphic and Photo Sources: City of Forest Grove, Peter J. Edwards *CHR*, Forest Grove Historic Landmarks Board

SHPO Inventory No.:

CITY OF FOREST GROVE INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE SURVEY FORM

Name :
Address: 1928 Cedar Street
Resource #:

T/R/S: T 1.S, R.3 W. Sec. 6
Map No.: 1 S 3 6BA Tax Lot: 3600
Quadrangle: USGS Forest Grove 7.5'

Statement of Historical and Architectural Significance:

This house is very similar to the Gothic Revival at 1839 Ash Street. It features many of the typical Gothic Revival elements, including a steep gable roof with central wall dormers. The house has been altered slightly, as an original hip roof porch on the rear elevation has been enclosed. An additional shed lean to has been added to the rear of the enclosed porch. These modifications were done by the turn of the century.

This house is particularly threatened by the zoning of the area. The vacant land immediately to the north coupled with commercial zoning makes it probable that this house will be lost to development. In addition, the house and landscaping need maintenance.

However, the house is one of a very few Gothic Revival structures in the Forest Grove area and retains most of its integrity.

Sources: McAlester, *Field Guide to American Houses*, 1984.